

Examples of site remediation/recovery at Horseshoe Bend

In 2012 flood waters damaged the walking track. DEPI appointed a contractor to repair the track, however the contractor cleared a significant access track in breach of what was meant to happen. WGCMA managed the track remediation works and have been running a photopoint monitoring program to monitor the sites recovery. The following are some of the sites over that time.

